## 10/575532 IAP15 Rec'd PCT/PTO 12 APR 2006

U.S. National Stage Divisional Patent Application of Manfred Blumberg, et al. Attorney Docket No. 7701-0001WOUS-1 Claiming priority to PCT/EP2003/011568 filed 10/17/03

## NEUTRAL DATA COMPUTER CONTROL SYSTEM FOR A MACHINE TOOL USED TO PRODUCE WORKPIECES WITH A THREADED SURFACE AND ASSOCIATED MACHINE TOOL

"EXPRESS MAIL" MAILING LABEL NUMBER <u>EV 713350389 US</u>

April 12, 2006

I HEREBY CERTIFY THAT THIS PAPER OR FEE IS BEING DEPOSITED WITH THE UNITED STATES POSTAL SERVICE "EXPRESS MAIL POST OFFICE TO ADDRESSEE" SERVICE UNDER 37 C.F.R. 1.10 ON THE DATE INDICATED ABOVE AND IS ADDRESSED TO THE COMMISSIONER FOR PATENTS, P.O. BOX 1450, ALEXANDRIA, VA 22313-1450

Christine Rounds

untine

(TYPED OR PRINTED NAME OF PERSON MAILING PAPER OR FEE)

4

rí

(SIGNATURE OF PERSON MAILING PAPER OR FEE)

## 10/575532 IAP15 Rec'd PCT/PTO 12 APR 2006

Title: Neutral data computer control system for a machine tool for producing workpieces having a helicoidal generated surface with data carriers, data carrier signals, a computer system, a computer program and computer program products, and also an associated machine tool

[0001] The present invention relates to a neutral data computer control system for a machine tool with a computer system, a computer program and computer program products, and also an associated machine tool.

[0002] Against the background of increasingly interlinked production processes and their standardization in the industry, the problem that is nowadays the prime concern in the production of machine tools is that of also incorporating in this process the computer systems that are necessary for activating the machine tools. In this respect, one aim is to provide, extent technically possible, standardized machine control systems, offering the user greatest possible uniformity of the machine control parameters for the products from his range of workpieces - for instance when changing an actual machine type or else for improved data storage and archiving.

[0003] Such initiatives have already been pursued for some time for various types of machine tool, including for instance for bevel gear cutting machines, which are the focus of attention here.

For bevel gear cutting machines there are for [0004] solutions to this in which the relevant machine control parameters of an entire machine family are combined in a standardized data model with all the axes to be activated that come into consideration in the machine family, which then, in individual cases, is replicated on the respective machine actually concerned - to the extent to which this is possible - that is to activated by the axes machine control parameters are also actually present.

[0005] For gear cutting machines for the form milling or grinding of workpieces having a helicoidal generated surface, that is to say in particular spur

gears, worms and rotors, such a system does not exist as yet - although it would of course also be desirable here for the reasons stated above.

[0006] The reason for this lies in a particular technical difficulty that has to be overcome in the form grinding of these workpieces: multiaxis positioning systems, as are also required by machine tools, need synchronization of the individual movements with one another, so that a defined curve is followed in three-dimensional space. This is achieved by one of the axes serving not only for its own positioning but also as a guiding axis for the synchronization of the other axes to be positioned.

[0007] Such a method according to the prior art can be found for instance in EP 0 784 525, which relates to a method of producing tooth flank modifications on bevel gears. The relevant axes are activated preferably by means of a polynomial function of the form

$$f(\Theta) = a_0 + \frac{a_1}{1!} \cdot \Delta\Theta + \frac{a_2}{2!} \cdot \Delta\Theta^2 + \frac{a_3}{3!} \cdot \Delta\Theta^3 + \frac{a_3}{4!} \cdot \Delta\Theta^4$$

where  $f(\theta)$  is the positioning function for the respective axis to be activated in dependence on the movement of the guiding axis  $\theta$ . The coefficients  $a_0$ ,  $a_1$ ,  $a_2$ ,  $a_3$  and  $a_4$  serve in this case as further parameters of the position control of the respective axis activated by the function  $f(\theta)$ .

[0008] According to the prior art, one of the mechanical axes of the machine tool to be activated always serves in this case as the guiding axis. In the case of bevel gear cutting machines, which operate by the generating method and therefore have a cradle, as also in the case of EP 0 784 525, usually this cradle,

which is always necessary, is used as the guiding axis; consequently, its generating movement is used as for the synchronization quiding movement of movements of the other axes. In this way there always exists - even irrespective of the further configuration of the respective machine type result of the generating machine axis which, as a process, can be used in a standard way as a guiding axis.

[0009] For form grinding machines on the other hand, which have no cradle or comparable axis, the problem of suitably choosing such a standardized guiding axis, or the question of possibly doing without it, immediately arises when attempting to standardize the machine control parameters for different machine types.

[0010] Ιt is of course also possible principle to do without such a standard quiding axis and instead to specify the axis respectively used in the individual case as the guiding axis in the machine control parameters. Creating such a possibility can already lead to a certain standardization machine control parameters. Nevertheless, this unsatisfactory, since, when changing a machine type to a machine which does not have the selected guiding axis, there is not only the problem of creating new machine control parameters for the guiding axis but also, on account of the dependencies described above of other axes on the quiding axis, always the immediate requirement of generating new machine control parameters for all the other axes that are dependent on the guiding axis. If, on the other hand, there is no other axis present as the guiding axis, it can attempted to achieve its positioning result on workpiece by other further axes that are instead present on the new machine type being activated by machine control parameters in a corresponding way, the

other axes with their respective machine control parameters remaining unaffected.

[0011] Thus, for instance, an absent positionable pivoting axis for the pivoting of the workpiece and tool with respect to each other by means of a rotation of the tool axis in the vertical can be replaced by a pivoting axis for the pivoting of the workpiece and the tool with respect to each other by means of a rotation of the workpiece axis in the horizontal, without the machine control parameters for instance of a radial infeed axis or a positionable rotating axis of a clamping head for the rotation of the workpiece in the workpiece holder being affected.

[0012] A precondition for this, however, is that a quiding axis that is standard for the entire control concept of all machine types coming into consideration can be specified. This condition is not met in the case of form grinding machines, as alreadv above, if only because here - by contrast with machines which operate on the basis of a generating method there is no generating movement that is always necessary and always able to serve as guiding a movement.

It is therefore the object of the present [0013] invention to provide a computer control system for a machine tool for producing workpieces having helicoidal generated surface which allows the use of the respective machine control parameters for different machine types with different activatable axes in such a way that, when changing the machine to be activated, as few machine control parameters as possible - within the limits of geometrical possibility - have to be newly formed for activating the axes.

This is achieved by a multiaxis machine tool for producing workpieces with a helicoidal generated surface which has a workpiece holder for receiving a a tool, activatable mechanical workpiece, axes machining the workpiece or for positioning the workpiece and the tool in relation to each other, and also an open-loop and/or closed-loop control device for activating axes, and which is characterized according to the invention in that there is provided at least one virtual axis, which can be parameterized as a guiding axis for other axes and then serves only for the synchronization of these other axes.

[0015] In this way there is created an additional virtual axis, which itself does not activate any mechanical axis of the machine tool, but nevertheless is able to synchronize other axes. This can take place for instance by an only time-dependent polynomial, as follows

$$L_{Virt}(t) = a_{virt,0} + a_{virt,1} \cdot t + a_{virt,2} \cdot t^2 + a_{virt,3} \cdot t^3$$

to be precise without the thereby determined value  $L_{Virt}\left(t\right)$  being used for the direct activation of a mechanical axis of the machine tool. Rather, this is included somewhat as follows

$$Achspos_{1}(L_{Virt}(t)) = a_{1,0} + a_{1,1} \cdot L_{Virt}(t) + a_{1,2} \cdot L_{Virt}(t)^{2} + a_{1,3} \cdot L_{Virt}(t)^{3}$$

$$Achspos_{2}(L_{Virt}(t)) = a_{2,0} + a_{2,1} \cdot L_{Virt}(t) + a_{2,2} \cdot L_{Virt}(t)^{2} + a_{2,3} \cdot L_{Virt}(t)^{3}$$

$$Achspos_{3}(L_{Virt}(t)) = a_{3,0} + a_{3,1} \cdot L_{Virt}(t) + a_{3,2} \cdot L_{Virt}(t)^{2} + a_{3,3} \cdot L_{Virt}(t)^{3}$$

with a synchronizing effect in the formation of the position values actually used for the activation of the mechanical axes,  $Achspos_i$  (here 3 axes, that is to say i = 1 to 3).

[0016] The provision of such a virtual axis consequently allows the formation of the axial positions for the activation of the mechanical axes to

be kept completely independent of any actual movement each axis of the machine tool, whereby therefore possible when changing the machine to activated within limits of \_ the geometrical possibility - newly to form only the machine control parameters which serve for the activation of axes that are additionally present in the new machine. other hand, the machine control parameters for axes that are to be encountered before and after the change of the machine are retained. In the case of the aforementioned polynomials, this means for instance that the coefficients ai, defining the path curve do not have to be newly formed for these axes.

[0017] With respect to the term used here, virtual axis, it should be noted with regard to the use of this term in the prior art that this is standard terminology to the extent that it concerns an axis formed only in the respective open-loop and/or closedloop control device that is used, having no direct equivalent in the mechanical axes of the respective machine tool that are actually present. Differences from the prior art, for instance according to DE 42 91 exist here however to the extent that the virtual axis there (sometimes also referred to there as the soft axis) serves for the direct activation of actual mechanical axes, from which the virtual axis there is combined to a certain extent on a software By contrast, the virtual axis in the sense of the present invention here does not serve actual activation of mechanical axes, in particular not for any software synthesis of additional axes finding an equivalent in the mechanical reality of the machine tool to be activated, but only for the synchronization of the activation of other axes.

[0018] Accordingly, the success according to the invention is also achieved by a method of activating a

multiaxis machine tool according to the invention, a virtual axis initially being parameterized as a guiding axis for other axes, and then, during the operation of the machine for machining the workpiece, the other axes merely being synchronized in their positioning with the aid of this virtual guiding axis.

[0019] The multiaxis machine tool according to the invention preferably has at least five activatable mechanical axes for the positioning of the workpiece and the tool in relation to each other, which permits the fabrication of rotationally symmetrical workpieces. If it is also desired to fabricate non-rotationally symmetrical workpieces, such as worms for instance, at least one additional axis is needed, provided for the pivoting of the workpiece and the grinding wheel with respect to each other in the horizontal, as still to be explained.

[0020] In a particularly preferred way, the multiaxis machine tool according to the present invention is characterized in that a grinding wheel is provided as the tool and, as mechanical axes, at least one

- positionable radial infeed axis, also designated by  $\chi$ , is provided for the grinding wheel,
- a grinding slide which can be positioned horizontally and orthogonally in relation to the radial infeed axis, also designated by  $\zeta$ , is provided for the positioning of the grinding wheel in the direction of displacement of the grinding slide,
- a positionable rotating axis, also designated by  $\beta$ , of a clamping head is provided for the rotation of the workpiece in the workpiece holder,

- a positionable pivoting axis, also designated by  $\tau$ , is provided for the pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the grinding wheel axis or its parallel projection in the vertical plane, also designated by B, and
- a rotating axis, also designated by  $\boldsymbol{\omega}_{\text{r}}$  is provided for the driving of the grinding wheel.
- [0021] A positionable displacing axis, also designated by  $\delta$ , for the monitoring of a displacing position of the grinding wheel along the grinding wheel axis, may also be provided as a mechanical axis.
- [0022] The multiaxis machine tool according to the invention preferably also has a pivoting axis, also designated by  $\sigma$ , as a mechanical axis for the pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the grinding wheel axis or its parallel projection in the horizontal plane, also designated by A, which also allows the already mentioned fabrication of non-rotationally symmetrical workpieces.
- [0023] As an alternative or in addition, this may also be achieved by a mechanical pivoting axis, also designated by , for the pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the workpiece axis or its parallel projection in the horizontal plane, also designated by A.
- [0024] Furthermore, a displacing axis, also designated by , may be provided as a mechanical axis, serving for the vertical displacement of the workpiece and the grinding wheel with respect to each other.

[0025] The virtual axis itself is formed particularly preferably by the open-loop and/or closedloop control device by means of a freely selectable function or relation, which is dependent particularly preferred time way on and in one embodiment of the present invention only on time. However, it is equally possible to make the virtual axis not dependent on time but on other events or values - possibly also external events or values - for instance positions reached by external machines, such as robots.

[0026] The embodiment of the present invention which forms the virtual axis by means of a freely selectable function or relation also has some special advantages:

[0027] During the grinding of workpieces having a helicoidal generated surface, such as for instance spur gears (of a helicoidal surface which sometimes also has a zero pitch of the thread, namely in the case of straight teeth), worms or rotors, it is frequently the case that a single non-virtual guiding axis is often not adequate here for the entire workpiece fabrication process, since its quiding movement often becomes too minimal, in view of the limited numerical accuracy in reality, to allow activating functions (or relations) with sufficient movement still to be calculated for the axes in dependence on it. This becomes particularly clear for instance for the case where a grinding slide which can be positioned horizontally and orthogonally in relation to a radial infeed axis is used for instance as a guiding axis for the positioning of the grinding wheel in the displacing direction of grinding slide, and then edge an orthogonally in relation to the workpiece rotating axis is to be milled on the workpiece, for instance as a termination of a helicoidal generated surface, occurs for instance in the case of workpieces which

have a number of helicoidal surfaces that are separated from one another, for instance by round axial portions, or are at least different in terms of their geometry. (In this connection it should be stated that workpieces with such partial or portional helicoidal surfaces are regarded as workpieces having a helicoidal generated surface in the sense of the present invention.) In the aforementioned case this is so because the movement of the grinding slide comes completely to a standstill at the point of the perpendicular to the workpiece axis, and consequently can no longer serve as a guiding movement even without limited numerical resolution; the grinding slide is consequently unusable as a guiding axis at this point. It is therefore necessary to carry out a change of the guiding axis at such points, which makes standardized machine control parameters different machine models all the more difficult, since in the case of a change of machine type, the difficulties already mentioned at the beginning adaptation to the new machine sometimes occur for each guiding axis used. Moreover, it should be noted that such a change of axis also always leads to undesired fabrication marks on the workpiece to be created at the point of the workpiece where the change is performed, account of the associated discontinuity of the activation of the axes.

[0028] While the virtual axis according to present invention can be formed by means of a freely selectable function or relation, this can take place in way that this virtual guiding axis requirements throughout the entire fabrication process without changing the guiding axis, since in this way dependence of the guiding axis caused by the fabrication process can be avoided on account of the complete freedom in its choice. In this way, the present invention is advantageously also suitable for the case of operating only a single machine type that

comes into consideration, since in this case no problems of the type described at the beginning in respect of changing the guiding axis occur any longer when the freely selectable virtual axis according to the invention is used, and consequently no resultant defects occur any longer on the workpieces. If, on the other hand, the virtual guiding axis is chosen to be unchanging, process-related dependencies possibly cannot be ruled out, which may then lead to the already mentioned numerically unfavourably conditioned systems.

[0029] As already explained in the example given above, a polynomial function comes into consideration in particular as the freely selectable function, but so too does for example a circular relation. A freely selectable relation may also similarly be defined by a table of values.

[0030] The activation of the respective mechanical axis by the open-loop and/or closed-loop control device may also take place by means of a freely selectable function or relation, the respective mechanical axis preferably being dependent, as also already explained above, on the value of a virtually formed axis acting as a guiding axis, in order in this way to achieve the synchronization of the axial positions with respect to one another.

[0031] Of course, the respective axis may in this case also be made dependent on the value of further parameters, for instance for the activation of the desired positional values. As already explained, a polynomial function, which is also dependent on the value of one of the virtual axes and polynomial coefficients, may serve in this case as the freely selectable function.

[0032] However, similarly suitable as the freely selectable relation for the respective mechanical axis is a circular relation, which is dependent on the value of one of the virtual axes and circle constants, preferably a circle radius and a centre point, given by a pair of coordinates, and also a direction of rotation.

[0033] The same applies to the activation of the respective mechanical axis, which takes place by the open-loop and/or closed-loop control device by means of a freely selectable relation which is given by a table of coordinates, and similarly for all other functions and/or relations that appear to be suitable for achieving the desired workpiece geometry.

[0034] In the case of use of a relation formed by a table of coordinates, this is preferably formed by an X coordinate, a Y coordinate and a normal angle, preferably as viewed in end-on section.

[0035] In a further preferred embodiment according to the present invention, the multiaxis machine tool is characterized in that a memory is also provided, stored in which are machine control parameters which are accessed by the open-loop and/or closed-loop control device, which permits flexible realization of the present invention by a computer control system.

[0036] This is so because a data structure which allows the parameterization of the virtual axis as a guiding axis for other axes can be provided in this memory, it also being possible that here there is a data structure which also allows the parameterization of any mechanical axis as a guiding axis for other axes, for instance to allow older machine control parameters that are not yet adjusted to the computer control system according to the invention to be used.

[0037] The definition of the function or relation for the formation of the virtual axis and also the definition of the function or relation for the activation of the respective mechanical axis by the open-loop and/or closed-loop control device can also be flexibly stored in the memory.

In this case, data fields may serve for the 188001 identification of predefined types of function or types of relation, used for the definition of a function or relation of the respective mechanical axis. predefinition of frequently used types of function and/or relation makes it easier here for the definition Preferably coming into to be stored in the memory. consideration as types of function predefined in such a polynomial for instance a function, way are of sixth degree, with instance the polynomial parameters, or else coefficients as once again circular relation with a circle radius and a centre point, given by a pair of coordinates, and a direction of rotation as parameters. Similarly, however, a table of coordinates with coordinates as parameters may be predefined as a type of relation, an X coordinate, a Y coordinate and a normal angle, preferably as viewed in end-on section, preferably being used in each case as coordinates.

[0039] In further preferred embodiment а multiaxis machine tool according to the invention, in the memory in which the machine control parameters accessed by the open-loop and/or closed-loop control device are stored there is a data structure which is intended for receiving an identification of the workpiece flank being machined by the activation of the respective mechanical axis by the open-loop and/or closed-loop control device, preferably identification for a flank on the right or on the left. This parameter is required by the machine in the case of non-symmetrically formed grinding wheels, such as for instance for the fabrication of worms, in order to move to the respective flank with the correct side of the tool. This control parameter also permits open-loop or closed-loop control of the force in a way corresponding to the respective flank.

[0040] In the memory in which machine parameters accessed by the open-loop and/or closed-loop device are stored there is also control structure which combines at least one group of machine control parameters corresponding to a partial region of the workpiece, as a segment under a common segment identification, preferably a segment number, it being that machine preferred such a group of parameters for which the same axis is parameterized as the guiding axis are always combined as a segment.

[0041] The structuring of the machine control parameters into segments makes it possible to replicate a segmentation of the workpiece that exists in reality structuring of in the the machine parameters, which improves their overall clarity and consequently also the possibility of their assignment to the first cuts made on workpieces.

[0042] The embodiments described above of multiaxis machine tool according to the invention with a memory consequently serve for the replication in this memory of machine control parameters which initiate during the operation of the machine machine functions However, this can take for workpiece fabrication. place not only by storage in the memory of the machine, but also by reading in a data carrier provided with corresponding machine control parameters, such as for instance a floppy disc, a CD or else a DVD, or else by reading an electronic carrier signal with these machine control parameters into the multiaxis machine tool according to the invention, for instance via a data line, as preferably also used in a data network. Such a data carrier or such a data carrier signal is in this case constructed in a way corresponding to the present invention for reading the data constructed according to the invention as described above into the multiaxis machine tool according to the invention for controlling the latter in a way corresponding to the present invention.

[0043] In every case, such a data carrier or such an electronic carrier signal is parameterized according to the invention with machine control parameters for reading into a multiaxis machine tool, the data carrier or the electronic carrier signal having on it at least one data structure which has a data field which allows the parameterization of the virtual axis as a guiding axis for other axes, and the data carrier or the electronic carrier signal activating the machine tool during the reading-in or after the reading-in by means of this data structure on the basis of the method according to the invention stated above.

[0044] Also serving for carrying out the present invention is a method of generating machine control a multiaxis machine tool which parameters for is characterized according to the invention in that generates a data carrier or an electronic carrier signal with machine control parameters as described It goes without saying that this method may also be realized on a computer system with at least one data processing unit and at least one memory, usually for instance as a computer program, it having the corresponding instructions set up for carrying out the Such a computer program may in this case take any form, but in particular also that of a computer program product on a computer-readable medium, such as for instance a floppy disc, CD or DVD, it having

computer program coding means, with which, after loading the computer program, a computer is in each case made by the program to carry out the method according to the invention. It may, however, also be for instance in the form of a computer program product which has a computer program on an electronic carrier signal, with which, after loading the computer program, a computer is in each case made by the program to carry out the method according to the invention.

[0045] The different individual elements of the present invention described above, seen in their entirety, can provide a neutral data computer control system for a multiaxis machine tool for producing workpieces having a helicoidal generated surface with

- a computer system according to the invention for generating machine control parameters multiaxis machine tool with least one at processing unit and at least one memory, the data processing unit being set up in programming terms in such a way that it generates at least one data an carrier or electronic carrier signal machine control parameters according to the present invention, or
- such a computer program or computer program product,
- and at least one multiaxis machine tool according to the invention.

[0046] Further details of such a system according to the present invention can be taken from the exemplary embodiments.

[0047] Exemplary embodiments of the present invention, which are to be understood as non-

restrictive, are discussed below on the basis of the drawing, in which:

[0048] Figure 1 shows a neutral data computer control system according to the invention for a multiaxis machine tool for producing workpieces having a helicoidal generated surface,

[0049] Figure 2 shows an abstract model of a multiaxis machine tool according to the invention for producing workpieces having a helicoidal generated surface with diverse mechanical axes, and

[0050] Figure 3 shows a workpiece having a helicoidal generated surface for being produced on a multiaxis machine tool according to the invention.

[0051] Figure 1 shows neutral data computer a to the invention control system according for multiaxis machine tool for producing workpieces having a helicoidal generated surface, to be precise

with

- a computer system 1 according to the invention for generating machine control parameters for a multiaxis machine tool 2, 2a with at least one data processing unit and at least one memory, the data processing unit being set up in programming terms in such a way that it generates here in a data network an electronic carrier signal 3 with machine control parameters according to the present invention,
- and a first multiaxis machine tool 2 according to the invention and a second such machine tool 2a.

[0052] In the present case, the situation therefore such that the first machine 2 has (along with other axes) a mechanical pivoting axis  $\sigma$ pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the grinding wheel axis or its parallel projection in the horizontal plane A; a possibility which the second machine 2a does not have. However, the latter does pivoting axis y for the pivoting a workpiece and the grinding wheel with respect to each other by means of a rotation of the workpiece axis or its parallel projection in the horizontal plane A. the present neutral data computer system, it is thus easily possible to use machine control parameters generated by the computer system 1 for the first machine 2 according to the invention also for the second machine tool 2a according to the invention if the generated machine control parameters make use of a according quiding axis to the present invention. Both machines 2, 2a have a virtual guiding axis, so that, when there is a change of machine from the first machine 2 to the second machine 2a, only the machine control parameters for the pivoting axis y instead of the pivoting axis  $\sigma$  have to be formed. the other machine control parameters, on the other hand, can be retained, since they are coupled by the virtual guiding axis.

[0053] Figure 2 shows an abstract model (covering various actual configurational possibilities) of a multiaxis machine tool according to the invention for producing workpieces having a helicoidal generated surface with diverse mechanical axes, to be precise with

<sup>-</sup> a positionable radial infeed axis  $\chi$  for the grinding wheel,

- a grinding slide  $\zeta$  which can be positioned horizontally and orthogonally in relation to the radial infeed axis, for the positioning of the grinding wheel in the direction of displacement of the grinding slide,
- a positionable rotating axis  $\beta$  of a clamping head for the rotation of the workpiece in the workpiece holder,
- a positionable pivoting axis  $\tau$  for the pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the grinding wheel axis or its parallel projection in the vertical plane B,
- a rotating axis  $\boldsymbol{\omega}$  for the driving of the grinding wheel,
- a positionable displacing axis  $\delta$  for the monitoring of a displacing position of the grinding wheel along the grinding wheel axis,
- a pivoting axis  $\sigma$  for the pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the grinding wheel axis or its parallel projection in the horizontal plane A,
- a displacing axis  $\eta$  for the vertical displacement of the workpiece and the grinding wheel with respect to each other, and
- a pivoting axis γ for the pivoting of the workpiece and the grinding wheel with respect to each other by means of a rotation of the workpiece axis or its parallel projection in the horizontal plane A

for better illustration of the geometrical relationships taken as a reference.

[0054] Figure 3 shows a workpiece having helicoidal generated surface for being produced on a multiaxis machine tool according to the invention, with With reference to the abstract 9 different segments. model illustrated in Figure 2, the machine control are to be specified below parameters corresponding to the present invention by way example for the segment 8, a conical kneading element Seg. 8, the virtual guiding axis being designated here by K:

Guiding axis: κ			$X_{\mathtt{Start}}$	X <sub>End</sub>	A	В	С	D	E	F	G
κ	[]	008=PB	0	1	0	1	0	0	0	0	0
η	[mm]	008=PB	0	1	0	0	0	0	0	0	0
γ	[rad]	008=PB	0	1	0	0	0	0	0	0	0
ω	[m/s]	008=PB	0	1	40.0	0	0	0	0	0	0
τ	[rad]	008=PB	0	1	0.00706	0.000027	0	0	0	0	0
δ	[mm]	008=PB	0	1	0.0	0	0	0	0	0	0
σ	[rad]	008=PB	0	1	0	0	0	0	0	0	0
٤	[mm]	008=PB	0	1	0	0.3183	0	0	0	0	0
β	[rad]	008=PB	0	1	0	0.00395	0	0	0	0	0
χ	[ mm ]	008=PB	0	1	90.17	-0.0797	0	0	0	0	0

Table 1: Segment 008: 2nd conical kneading element Process: roughing

[0055] To explain such a table (not all the options are used above in Table 1), which reproduces an embodiment of the functional data structures according to the present invention:

Column 1: Designation of axis

Column 2: Unit

Column 3: Segment number = code letter for the type of neutral data (to be precise C for circle, P for polygon [of the 6th

degree], K for coordinates [points] of a table of coordinates) and code letter for which flank (R for right flank; L for left flank; B for both flanks)

Other columns: Table values with  $X_{\text{Start}}$  and  $X_{\text{End}}$  as range limits and the values for parameters A, B, C, D, E, F and G (in the case of a polygon), R, A, B, C (in the case of a circle) and A, B, C (in the case of a table of coordinates) with respect to the relations and/or functions on the basis of the following:

$$R = \sqrt{(x-A)^2 + (y-B)^2}$$

Circle [C as code letter]:

with the value in column R as radius, C as direction of rotation, with -1 indicating the clockwise direction of rotation (cw) and the value +1 indicating the counterclockwise direction of rotation (ccw)

polynomial [P as code letter]:  $Y = A + B \cdot x + C \cdot x^2 + D \cdot x^3 + E \cdot x^4 + F \cdot x^5 + G \cdot x^6$ 

coordinates (points) of a table of coordinates [K as code letter]:

value in column A: X coordinate, value in column B: Y coordinate, value in column C: normal angle, always stored in end-on section

## Examples:



